



Repair Pricing Jan 2011

Barrel Work

Make and fit bead sight	£36.00
Re Black	£220.00
Re Black (Best Quality)	£264.00
Re Brown	£324.00
Re-sleeve Shotgun	£720.00
Tighten Action	£106.00
New Striker	£96.00
Supply and fit top lever spring	£105.00
Supply and fit ejector spring	£144.00
Supply and fit Box lock main spring	£116.00
Supply and fit Side lock main spring (English) from	£468.00
Supply and fit Side lock mainspring (Spanish) from	£145.00
Re-joint action	£298.00

Servicing

Box lock non-ejector	£170.00
Box lock ejector	£195.00
Side lock non-ejector	£195.00
Side lock ejector	£252.00
Pump/Semi-Auto	£120.00
Over and under	£195.00
Black and blue parts after service from	£132.00

Stock Work

Lengthen in wood	£288.00
Lengthen in vulcanite	£204.00
Supply and fit recoil pad	£146.00
Supply and fit leather covered recoil pad	£456.00
Supply and fit silvers pad	£216.00
Shorten stock re-fit plate	£108.00
Fit Oval	£144.00
Oil finish woods	£600.00
Numbering	£380.00

Please allow approximately + or – 10% on any quotes given as charges are largely based on time taken to carry out repairs. As such, the above prices are only a guideline.

- *All prices quoted above are inclusive of VAT at the current rate of 20%*
- *Any work not mentioned above will be quoted separately.*
- *All work is undertaken at the clients own risk and neither the WLGR nor the Gunsmith can be held responsible for any damage that can occur whilst the gun (s) are being altered, repaired or serviced.*