



### **Barrel Work**

Make and fit bead sight	£50
Raise dents and lap out	£100
Re-black	£195
Re-brown	£255
Re-fix ribs, repair and black	£490
Alter choke (per barrel)	£65
Re-sleeve	POA
Re-barrelling	POA
Deactivate double barrel	£230

### **Action Work**

Tighten action	£105
Re-joint action by welding hooks and bites	£130
Re-joint action short screw pin	£255
New top lever spring, wire cut	£90
New ejector spring, wire cut	£120
New box-lock main spring, wire cut	£105
New side-lock main spring, wire cut	£120
Hand made English main springs	POA
New striker	£85
New tumbler nose, A & D action	£140
Re-black furniture	£115
Strip, clean and regulate box-lock non-ejector	£150
Strip, clean and regulate box-lock ejector	£180
Strip, clean and regulate side-lock non ejector	£180
Strip, clean and regulate side-lock ejector	£220
Strip, clean and regulate pump or semi-auto	£110
Strip, clean and regulate over and under	£180
Regulate pulls, one hand	£90
Regulate pulls, both hands	£150
Regulate ejectors	£60
New extractor guide leg	£65
Shoot and test with 25 cartridges	£30
De-Activated shotgun (inc. proof)	£230
De-Activated single barrel shotgun (inc. proof)	£175

## Stock Work

Lengthen in wood up to 1 “(high grade extra)	£290
Over 1”, each additional ½”	£40
Lengthen in vulcanite up to 1” (vulcanite extra)	£200
Make and fit wooden comb raiser	£420
Set stock one way (at customers own risk)	£100
Set stock two ways (at customers own risk)	£135
Fit Silvers pad (cost of pad extra)	£195
Supply and fit leather pad (1” Max)	£490
Fit continental type pad (cost and pad extra)	£105
Re-finish woods, French Polish	£180
Re-finish woods, with drop points, French Polish	£220
Rounded pistol grip	£230
Re-finish woods, oil finish	£510
Re-finish woods, with drop points, oil finish	£750
Re-checker stock and forend	£245
Shorten stock, checker end	£180
Shorten stock, re-fit pad (if possible)	£150
Shorten stock, re-fit plate	£150
Fit oval (cost of oval extra)	£130
Re-stocking	POA
Engraving	POA
Initials	£45
Numbering	£370

- *Please allow approximately + or – 10% on any quotes given as charges are largely based on time taken to carry out repairs. As such, the above prices are only a guideline.*
- *All prices quoted above are inclusive of VAT at the current rate of 15%*
- *Any work not mentioned above will be quoted separately.*
- *When altering or repairing any wooden part any such work is done at the clients risk.*